OUT59445

1966 AUG 15 21 50 Z

25X1

1 6 AUG 1966 25X1

- S E C R E T 152129Z CITE 8108
- 1. CAMERA B-15 WAS USED IN MISSION 8112 FLOWN ON 13 AUGUST 1966. PROCESSING WAS ACCOMPLISHED BY NAV RECON TECH SUPPCEN.
 - 2. ORIGINAL NEGATIVE:
 - A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD.
- B. 9R SIDE: TWO ROWS OF MINUS DENSITY DOTS LOCATED 1.1 INCHES AND 2.9 INCHES FROM THE INBOARD SIDE, A DISTANCE OF 1.7 INCHES APART, ARE PRESENT THROUGHOUT THE MISSION. HEAT SPLICES ARE LOCATED BEWTEEN FRAMES 301/302, 601/602, 1501/1502 AND THROUGH FRAME 848. A MANUFACTURING SPLICE IS PRESENT THROUGH FRAME 761. FOG IS PRESENT TO THE RIGHT OF THE CLOCK ON EACH FRAME.
- C. 9L SIDE: THREE ROWS OF MINUS DENSITY DOTS ARE PRESENT

 1.5 INCHES, 1.6 INCHES, AND 4.8 INCHES FROM THE OUTBOARD EDGE AND

 ARE LOCATED 1.7 INCHES APART. HEAT SPLICES ARE LOCATED BETWEEN

 FRAMES 102/103, 615/616/ 1080/1081, 1541/1542, 1553/1554, AND

 THROUGH 872. A MANUFACTURING SPLICE IS PRESENT ON FRAME 1681.

 EDGE STATIC OCCURS ALONG THE OUTBOARD EDGE THROUGHOUT THE MISSION.
- D. BOTH SIDES: EDGE FOG AND MINOR ROLLER CHATTER ON THE INBOARD SIDE ARE PRESENT THROUGHOUT. EMULSION DEFECTS, BLISTERS, AND PINHOLES ARE PRESENT INTERMITTENTLY THROUGHOUT. EXAMPLES ARE 9R 933, 1065, 303, 316, 317, 695. THE LAST TITLED FRAME IS 1724.
- E. THE CAMERA METERING WAS SLIGHTLY IRREGULAR ON THE RIGHT SIDE AND BETWEEN FRAMES ONE AND TWO OF THE LEFT SIDE. THERE

Mdvanca GOD)

PAG

DIAXX-

W3.4-LO



WAS NO MAJOR PROCESSING MALFUNCTIONS DURING THE MISSION.

- 3. POSITIVE:
 - A. THE PI SUITABILITY IS GOOD.
 - B. THE PRINTING AND PROCESSING IS GOOD.
- C. CLOUDS DEGRADED OR OBSCURED 60 PERCENT OF THE MISSION.
 SECRET

-- END OF MESSAGE--